

Menu

HISTORY FILE MAP for year 2003


REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

077.00:15-00:45 30m 1024bps realtime data lost due to use of incorrect
uplink sweep rate at DSS-24. The resulting uplink sweep
took 27m. Tune out at the end of uplink activity resulted
in the loss of a further 16m 1024 bps realtime data.
DR G102494 refers.



080.03:34-03:36 Command abort at DSS-24 due to transmitter power
fluctuations. Transmitter recalibrated and commands
transmitted with 30m delay. 5 minutes realtime 1024 bps
data lost due to additional 2-way->1-way->2-way
transitions. DR G102512 refers.